

ATTACHMENT A  
NOTICES OF ANOMALY

---

WYLE LABORATORIES, INC.  
Huntsville Facility



<b>ORIGINAL</b>		<b>NOTICE OF ANOMALY</b>	DATE: 07/11/2013
NOTICE NO: 1	F.O. NUMBER: ES&S-MSA-TA029	CONTRACT NO: N/A	
CUSTOMER: ES&S		WYLE JOB NO: T71013.01	
NOTIFICATION MADE TO: Paul Huffman		NOTIFICATION DATE: 07/11/2013	
NOTIFICATION MADE BY: Ryan Chambers		VIA: In person	
CATEGORY: [X] SPECIMEN    PROCEDURE    TEST EQUIPMENT		DATE OF ANOMALY: 07/11/2013	
PART NAME: DS200	PART NO. DS200		
TEST: Lightning Surge Test (LST)		I.D. NO. DS0313350009	
SPECIFICATION: VVSG Volume I			
PARA. NO. Section 4.1.2.7			
<b>REQUIREMENTS: 2005 VVSG Volume I: Section 4.1.2.4</b>			
Vote scanning and counting equipment for paper-based systems, and all DRE equipment shall be able to withstand, without disruption of normal operation or loss of data, surges of:			
a. +2 kV AC line to line			
b. +2 kV AC line to earth			
*c. + or - 0.5 kV DC line to line >10m			
*d. + or - 0.5 kV DC line to earth >10m			
*e. +1 kV I/O sig/control >30m			
*Indicates requirements that do not apply to the Unit Under Test (UUT), due to the fact that UUT does not contain DC lines in excess of 10 Meters, nor does it contain any I/O lines greater than 30 meters.			
<b>DESCRIPTION OF ANOMALY:</b>			
After the being subjected to the Lightning Surge Test (LST) being performed on July 11, 2013 the AC Power Adapter ceased to function and as a result, the DS200 suffered a disruption of normal operation. The AC Power Adapter ceased to function, during application of 2 kV. The failure occurred at pulse 3 of 7 Sync: 0°/60Hz between the Path L1--N. Photographs were taken of the testing site.			
Component Description: AC Power Adapter			
Manufacturer: Power-Win Technology Corp.			
Model: PW-080A2-1Y24AP			
(The remainder of this page intentionally left blank)			



NOTICE OF ANOMALY

<b>DISPOSITION • COMMENTS • RECOMMENDATIONS:</b> The final disposition is pending a root cause analysis to be presented by the client.	
Potential 10 CFR Part 21 <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
RESPONSIBILITY TO ANALYZE ANOMALIES AND COMPLY WITH 10 CFR PART 21: <input checked="" type="checkbox"/> CUSTOMER <input type="checkbox"/> WYLE	
CAR Required: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	CAR No.
VERIFICATION:	PROJECT ENGINEER: <u>ALS 7/17/13</u>
TEST WITNESS: <u>[Signature] 7/17/13</u>	PROJECT MANAGER: <u>[Signature] 07/17/13</u>
REPRESENTING: <u>ES&amp;S</u>	INTERDEPARTMENTAL COORDINATION: <u>N/A</u>
QUALITY ASSURANCE: <u>[Signature] 7/17/13</u>	

(The remainder of this page intentionally left blank)



Field Issue Resolution Process

Date Reported		7/11/2013
Report Date		9/6/2013
Who is Reporting the Issue?		Ryan Cisneros
Brief Description of the Issue		Power supply damaged during test (RCA #1 & #2)
Supplemental Information	What location is reporting the issue?	Wyle Labs
	Equipment Affected (Model & Hdw line)	DS(X) 1.3
	What Version of Software are They Running	FLEVS1500
	Has this Issue Been Confirmed or Duplicated	Yes
	By Who	Paul Huffman
	How	Lightning Surge Test

Implement Action Plan

1. Assign Field Issue Tracking Number		
2. Notify Ring Acct Mgr, Cust Svc Mgr, Cert		Joe McKay
3. Assess Warehouse Inventory as required		na
4. Categorize Issue	Software	Notify Dir: na Submit RCR: na
	Hardware	Notify Dir: Paul Huffman Identify Product Line Manager: Paul Huffman Is situation trivial?: NO
5. Conference Call Date: _____	What are the customer expectations?	Short Term: na Long Term: _____
	Immediate customer action	
	Is info gathered sufficient to resolve?	
	Engineering site visit required?	Yes
6. Find Root Cause	Arrange return of equipment?	no
	Wear/Handling? _____	How to fix? Add Tripp-Lite Spike Cube
	Design? _____	What prevents future occurrences? Add to QC checklist
	Other? Facility Capacitor _____	
7. Confirm Solution		Describe how fix was verified: Retest at Wyle was successful
		How does this solution impact the certified configuration? Official testing already complete
		What additional customer testing required? na

WYLE LABORATORIES, INC.  
 Huntsville Facility



<b>ORIG 1481</b> NOTICE OF ANOMALY		DATE: 07/12/2013
NOTICE NO: 2	P.O. NUMBER: ES&S-MSA-TA029	CONTRACT NO: N/A
CUSTOMER: ES&S		WYLE JOB NO: T71013.01
NOTIFICATION MADE TO: Paul Huffman		NOTIFICATION DATE: 07/12/2013
NOTIFICATION MADE BY: Ryan Chambers		VIA: In person
CATEGORY: <input checked="" type="checkbox"/> SPECIMEN <input type="checkbox"/> PROCEDURE <input type="checkbox"/> TEST EQUIPMENT		DATE OF ANOMALY: 07/12/2013
PART NAME: DS200	PART NO. DS200	
TEST: Lightning Surge Test (LST)		I.D. NO. DS0313350009
SPECIFICATION: VVSG Volume I		
PARA. NO. Section 4.1.2.7		
<b>REQUIREMENTS: 2005 VVSG Volume I: Section 4.1.2.4</b>		
Vote scanning and counting equipment for paper-based systems, and all DRE equipment shall be able to withstand, without disruption of normal operation or loss of data, surges of:		
a. +2 kV AC line to line		
b. +2 kV AC line to earth		
*c. + or - 0.5 kV DC line to line >10m		
*d. + or - 0.5 kV DC line to earth >10m		
*e. +1 kV I/O sig/control >30m		
*Indicates requirements that do not apply to the Unit Under Test (UUT), due to the fact that UUT does not contain DC lines in excess of 10 Meters, nor does it contain any I/O lines greater than 30 meters.		
<b>DESCRIPTION OF ANOMALY:</b>		
After the being subjected to the Lightning Surge Test (LST) being performed on July 12, 2013 the AC Power Adapter ceased to function and as a result, the DS200 suffered a disruption of normal operation. The AC Power Adapter ceased to function, during application of 2 kV. The failure occurred at pulse 4 of 7 Sync: 0°/60Hz between the Path L1--N. Photographs were taken of the testing site.		
Component Description: AC Power Adapter Manufacturer: Power-Win Technology Corp. Model: PW-080A2-1Y24AP		
(The remainder of this page intentionally left blank)		



NOTICE OF ANOMALY

<b>DISPOSITION • COMMENTS • RECOMMENDATIONS:</b> The final disposition is pending a root cause analysis to be presented by the client.	
Potential 10 CFR Part 21 <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
RESPONSIBILITY TO ANALYZE ANOMALIES AND COMPLY WITH 10 CFR PART 21: <input checked="" type="checkbox"/> CUSTOMER <input type="checkbox"/> WYLE	
CAR Required: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	CAR No.
VERIFICATION:	PROJECT ENGINEER: <u>MS 7/17/13</u>
TEST WITNESS: <u>[Signature] 7/17/13</u>	PROJECT MANAGER: <u>[Signature] 07/17/13</u>
REPRESENTING: <u>ES&amp;S</u>	INTERDEPARTMENTAL COORDINATION: <u>N/A</u>
QUALITY ASSURANCE: <u>[Signature] 7/17/13</u>	

(The remainder of this page intentionally left blank)



Field Issue Resolution Process

Date Reported		7/11/2013
Report Date		9/6/2013
Who is Reporting the Issue?		Ryan Cisneros
Brief Description of the Issue		Power supply damaged during test (RCA #1 & #2)
Supplemental Information	What location is reporting the issue?	Wyle Labs
	Equipment Affected (Model & Hdw line)	DS(X) 1.3
	What Version of Software are They Running	FLEVS1500
	Has this Issue Been Confirmed or Duplicated	Yes
	By Who	Paul Huffman
	How	Lightning Surge Test

Implement Action Plan

1. Assign Field Issue Tracking Number		
2. Notify Ring Acct Mgr, Cust Svc Mgr, Cert		Joe McKay
3. Assess Warehouse Inventory as required		na
4. Categorize Issue	Software	Notify Dir: na Submit RCR: na
	Hardware	Notify Dir: Paul Huffman Identify Product Line Manager: Paul Huffman Is situation trivial?: NO
5. Conference Call Date: _____	What are the customer expectations?	Short Term: na Long Term: _____
	Immediate customer action	
	Is info gathered sufficient to resolve?	
	Engineering site visit required?	Yes
6. Find Root Cause	Wear/Handling? _____	How to fix? Add Tripp-Lite Spike Cube
	Design? _____	What prevents future occurrences? Add to QC checklist
	Other? Facility _____	
	Capacitor _____	
7. Confirm Solution		Describe how fix was verified: Retest at Wyle was successful
		How does this solution impact the certified configuration? Official testing already complete
		What additional customer testing required? na

WYLE LABORATORIES, INC.  
 Huntsville Facility





NOTICE OF ANOMALY		DATE: 08/28/2013
NOTICE NO: <u>4</u>	P.O. NUMBER: <u>ES&amp;S-MSA-TA029</u>	CONTRACT NO: <u>N/A</u>
CUSTOMER: <u>Election Systems and Software (ES&amp;S)</u>		WYLE JOB NO: <u>T71013.01</u>
NOTIFICATION MADE TO: <u>Paul Huffman</u>		NOTIFICATION DATE: <u>08/13/2013</u>
NOTIFICATION MADE BY: <u>Ryan Chambers</u>		VIA: <u>In person</u>
CATEGORY: <input checked="" type="checkbox"/> SPECIMEN <input type="checkbox"/> PROCEDURE <input type="checkbox"/> TEST EQUIPMENT	DATE OF ANOMALY: <u>08/13/2013</u>	
PART NAME: <u>EVS 4.5.0.0 FL</u>	PART NO. <u>DS200</u>	
TEST: <u>Electromagnetic Susceptibility Test (EST)</u>	I.D. NO. <u>DS0313350009</u>	
SPECIFICATION: <u>EAC 2005 VVSG, Volume I</u>	PARA. NO. <u>Section 4.1.2.10</u>	
<b>REQUIREMENTS:</b>		
Vote scanning and counting equipment for paper-based systems, and all DRE equipment, shall be able to withstand an electromagnetic field of 10 V/m modulated by a 1 kHz 80% AM modulation over the frequency range of 80 MHz to 1000 MHz, without disruption of normal operation or loss of data.		
<b>DESCRIPTION OF ANOMALY:</b>		
The EUT was oriented at 180 degrees, with the back of the EUT facing the Antenna. The Antenna was oriented in the Vertical position. Upon exposure to an electromagnetic field of 10 V/m modulated by a 1kHz 80% AM modulation over the frequency range of 80 MHz to 1000 MHz, the DS200 suffered disruption of normal operation. The shoeshine setup menu was available on the display and the shoeshine ballot was hanging from the front of the DS200 paper path.		
<b>DISPOSITION • COMMENTS • RECOMMENDATIONS:</b>		
The final disposition is pending a root cause analysis to be presented by ES&S.		
Safety Related <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO Potential 10 CFR Part 21 <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A		
RESPONSIBILITY TO ANALYZE ANOMALIES AND COMPLY WITH 10 CFR PART 21: <input type="checkbox"/> CUSTOMER <input type="checkbox"/> WYLE		
CAR Required: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO CAR No. _____		
<b>VERIFICATION:</b>		PROJECT ENGINEER: <u>Ryan A. Hunt 08/30/2013</u>
TEST WITNESS: <u>N/A</u>	PROJECT MANAGER: <u>Michael Walker 8/30/13</u>	
REPRESENTING: <u>N/A</u>	INTERDEPARTMENTAL COORDINATION: <u>N/A</u>	
QUALITY ASSURANCE: <u>Deanna 8/30/13</u>	<u>N/A</u>	

WH 1066, Rev. March '09

Page 1 of 1

**WYLE LABORATORIES, INC.**  
 Huntsville Facility





Field Issue Resolution Process

Date Reported	8/28/2013	
Report Date	9/6/2013	
Who is Reporting the Issue?	Ryan Chambers	
Brief Description of the Issue	Shoe shine mode stops: (NSA #4)	
Supplemental Information	What location is reporting the issue?	Wyle Labs
	Equipment Affected (Model & H/w Rev)	DS200, J J
	What Version of Software are They Running?	FLEV34500
	Has this Issue Been Confirmed or Duplicated	Yes
	By Who:	Paul Hoffman
How	Electromagnetic Susceptibility Test	

Implement Action Plan

1. Assign Field Issue Tracking Number			
2. Notify Reg Acct Mgr, Cust Sec Mgr, Cert		Sue McRay	
3. Assess Warehouse Inventory as required		no	
4. Categorize Issue	Software	Notify Dir: Submit RCR: no no	
	Hardware	Notify Dir: Identify Product: Line Manager: Paul Hoffman Is situation critical?: no	
	5. Conference Call Date: _____	What are the customer expectations?	Short Term: no Long Term: no
		Immediate customer action	
6. Find Root Cause	Is info gathered sufficient to resolve?		
	Engineering site visit required?	Yes	
	Arrange return of equipment?	no	
	Workmanship? Wear/Handling? Design? Other? <u>Faulty Capacitor</u>	How to fix? Duplicate wrap sensor cable ferrite near scanner board. What prevents future occurrences?	
7. Confirm Solution		Describe how fix was verified: Tested at Wyle was successful How does this solution impact the certified configuration? Official testing already complete What additional customer testing required?	
U S C E	Release Planning	What's planned for this: Change manufacturing process documents	

WYLE LABORATORIES, INC.  
 Huntsville Facility



NOTICE OF ANOMALY		DATE: 08/28/2013
NOTICE NO: <u>5</u>	P.O. NUMBER: <u>ES&amp;S-MSA-TA029</u>	CONTRACT NO: <u>N/A</u>
CUSTOMER: <u>Election Systems and Software (ES&amp;S)</u>		WYLE JOB NO: <u>T71013.01</u>
NOTIFICATION MADE TO: <u>Paul Huffman</u>		NOTIFICATION DATE: <u>08/16/2013</u>
NOTIFICATION MADE BY: <u>Ryan Chambers</u>		VIA: <u>In person</u>
CATEGORY: <input checked="" type="checkbox"/> SPECIMEN <input type="checkbox"/> PROCEDURE <input type="checkbox"/> TEST EQUIPMENT	DATE OF ANOMALY: <u>08/16/2013</u>	
PART NAME: <u>EVS 4.5.0.0 FL</u>	PART NO. <u>DS200</u>	
TEST: <u>Electromagnetic Susceptibility Test (EST)</u>	I.D. NO. <u>DS0313350009</u>	
SPECIFICATION: <u>EAC 2005 VVSG, Volume I</u>	PARA. NO. <u>Section 4.1.2.10</u>	
<b>REQUIREMENTS:</b>		
Vote scanning and counting equipment for paper-based systems, and all DRE equipment, shall be able to withstand an electromagnetic field of 10 V/m modulated by a 1 kHz 80% AM modulation over the frequency range of 80 MHz to 1000 MHz, without disruption of normal operation or loss of data.		
<b>DESCRIPTION OF ANOMALY:</b>		
The EUT was oriented at 0 degrees, with the front of the EUT facing the Antenna. The Antenna was oriented in the Vertical position. Upon exposure to an electromagnetic field of 10 V/m modulated by a 1kHz 80% AM modulation over the frequency range of 80 MHz to 1000 MHz, the DS200 suffered disruption of normal operation. The following error was displayed on the DS200 "1003059: Event Log Write Failed" and the shoeshine ballot was hanging from the front of the DS200 paper path. When the EUT was unplugged from AC to be removed from the test chamber, the EUT unexpectedly shut off. The EUT would not power back on when only being supplied with DC power. When the EUT was plugged back into an AC outlet outside of the chamber, the EUT successfully powered on. After 5 minutes the plug was removed from the AC outlet, the EUT successfully switched to DC and displayed 75% power for the battery status. Within 3 minutes the EUT displayed 100% power. Within 1 minute the EUT displayed 50% power. Within 1 minute the EUT displayed 100% power.		
<b>DISPOSITION • COMMENTS • RECOMMENDATIONS:</b>		
The final disposition is pending a root cause analysis to be presented by ES&S.		
Safety Related <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Potential 10 CFR Part 21 <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	
RESPONSIBILITY TO ANALYZE ANOMALIES AND COMPLY WITH 10 CFR PART 21: <input type="checkbox"/> CUSTOMER <input type="checkbox"/> WYLE		
CAR Required: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	CAR No.	
VERIFICATION:	PROJECT ENGINEER: <u>Lynn A. Clark</u> <u>08/30/2013</u>	
TEST WITNESS: <u>N/A</u>	PROJECT MANAGER: <u>Michael P. Rubler</u> <u>8/30/13</u>	
REPRESENTING: <u>N/A</u>	INTERDEPARTMENTAL COORDINATION: <u>N/A</u>	
QUALITY ASSURANCE: <u>Successo</u> <u>8/30/13</u>	<u>N/A</u>	

WH 1066, Rev. March '09

Page 1 of 1

**WYLE LABORATORIES, INC.**  
 Huntsville Facility



Field Issue Resolution Process

Date Reported		8/28/2013
Report Date		9/6/2013
Who is Reporting the Issue?		Ryan Chambers
Brief Description of the Issue		Event Log write failed (MCA 45)
Supplemental Information	What location is reporting the issue?	Wyle Labs
	Equipment Affected (Model & How Rev)	DS200 J 3
	What Version of Software are They Running	FLEVS4500
	Has this Issue Been Confirmed or Duplicated	Yes
	By Who	Paul Hoffman
How		Electromagnetic Susceptibility Test

Implementation Action Plan

1. Assign Field Issue Tracking Number			
2. Notify Reg Acct Mgr, Cust Svc Mgr, Cert		Sue McKay	
3. Assess Warehouse Inventory as required		no	
4. Categorize Issue	Software	Notify Dir Submit RCN	
	Hardware	Notify Dir	
		Identify Product Line Manager	Paul Hoffman
		Is situation critical?	no
5. Conference Call Date: _____	What are the customer expectations?	Short Term Long Term	
	Immediate customer action		
	Is info gathered sufficient to resolve?		
	Engineering site visit required?	Yes	
6. Find Root Cause	Workmanship? _____	How to fix?	
	Wear/Handling? _____		
	Design? _____	What prevents future occurrences?	
	Other? Faulty Capacitor		
7. Confirm Solution	Describe how fix was verified.	Test at Wyle was successful	
	How does this solution impact the certified configuration?	Official testing already complete	
	What additional customer testing required?		
8. Release Planning	What's planned for this	Add copper tape during manufacturing process.	

WYLE LABORATORIES, INC.  
 Huntsville Facility



NOTICE OF ANOMALY		DATE: 08/28/2013
NOTICE NO: <u>6</u>	P.O. NUMBER: <u>ES&amp;S-MSA-TA029</u>	CONTRACT NO: <u>N/A</u>
CUSTOMER: <u>Election Systems and Software (ES&amp;S)</u>		WYLE JOB NO: <u>T71013.01</u>
NOTIFICATION MADE TO: <u>Paul Huffman</u>		NOTIFICATION DATE: <u>08/19/2013</u>
NOTIFICATION MADE BY: <u>Ryan Chambers</u>		VIA: <u>In person</u>
CATEGORY: <input checked="" type="checkbox"/> SPECIMEN <input type="checkbox"/> PROCEDURE <input type="checkbox"/> TEST EQUIPMENT	DATE OF ANOMALY: <u>08/17/2013</u>	
PART NAME: <u>EVS 4.5.0.0 FL</u>	PART NO. <u>DS200</u>	
TEST: <u>Electromagnetic Susceptibility Test (EST)</u>	I.D. NO. <u>DS0313350009</u>	
SPECIFICATION: <u>EAC 2005 VVSG, Volume I</u>	PARA. NO. <u>Section 4.1.2.10</u>	
<b>REQUIREMENTS:</b>		
<p>Vote scanning and counting equipment for paper-based systems, and all DRE equipment, shall be able to withstand an electromagnetic field of 10 V/m modulated by a 1 kHz 80% AM modulation over the frequency range of 80 MHz to 1000 MHz, without disruption of normal operation or loss of data.</p>		
<b>DESCRIPTION OF ANOMALY:</b>		
<p>The EUT was oriented at 0 degrees, with the back of the EUT facing the Antenna. The Antenna was oriented in the Vertical position. Upon exposure to an electromagnetic field of 10 V/m modulated by a 1kHz 80% AM modulation over the frequency range of 80 MHz to 1000 MHz, the DS200 suffered disruption of normal operation. The shoeshine setup menu was available on the display and the shoeshine ballot was hanging from the front of the DS200 paper path. When the EUT was unplugged from AC to be removed from the test chamber for ES&amp;S representative, the EUT unexpectedly shut off. The EUT would not power back on when only being supplied with DC power. When the EUT was plugged back into an AC outlet outside of the chamber, the EUT successfully powered on. After 5 minutes the plug was removed from the AC outlet, the EUT successfully switched to DC and displayed 75% power for the battery status.</p>		
<b>DISPOSITION • COMMENTS • RECOMMENDATIONS:</b>		
<p>The final disposition is pending a root cause analysis to be presented by ES&amp;S.</p>		
Safety Related <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO Potential 10 CFR Part 21 <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A		
RESPONSIBILITY TO ANALYZE ANOMALIES AND COMPLY WITH 10 CFR PART 21: <input type="checkbox"/> CUSTOMER <input type="checkbox"/> WYLE		
CAR Required: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO CAR No.		
<b>VERIFICATION:</b>		
TEST WITNESS: <u>N/A</u>	PROJECT ENGINEER: <u>Ryan A. Chambers 08/30/2013</u>	
REPRESENTING: <u>N/A</u>	PROJECT MANAGER: <u>Michael L. Walker 8/30/13</u>	
QUALITY ASSURANCE: <u>[Signature]</u>	INTERDEPARTMENTAL COORDINATION: <u>N/A</u>	
	QUALITY ASSURANCE: <u>N/A</u>	





Field Issue Resolution Process

Date Reported		3/28/2013	
Report Date		3/6/2013	
Who is Reporting the Issue?		Ryan Chambers	
Brief Description of the Issue		Unit shuts off when A/C removed. (NDA #6)	
Supplemental Information	What location is reporting the issue?	Wyle Labs	
	Equipment Affected (Model & How Rev)	DS200 J 3	
	What Version of Software are They Running?	FLEVS4500	
	Has this Issue Been Confirmed or Duplicated?	Yes	
	By Whom?	Paul Hultman	
	How?	Electromagnetic Susceptibility Test	
<b>Implement Action Plan</b>			
1. Assign Field Issue Tracking Number			
2. Notify Reg Acct Mgr, Cust Sec Mgr, Cert		Sue McKay	
3. Assess Warehouse Inventory as required		na	
4. Categorize Issue	Software	Notify Dir	na
		Submit RCR	na
	Hardware	Notify Dir	
		Identify Product Line Manager	Paul Hultman
5. Conference Call Date: _____	What are the customer expectations?	Is situation trivial?	yes
		Short Term	na
		Long Term	
6. Find Root Cause	Immediate customer action		
	Is info gathered sufficient to resolve?		
	Engineering site visit required?		Yes
	Arrange return of equipment?		no
Workmanship? _____ Wear/Handling? _____ Design? _____ Other? _____ Factory Capabilities	How to fix?	Replaced battery pack	
	What prevents future occurrences?		
7. Confirm Solution		Describe how fix was verified.	Reset at Wyle was successful
		How does this solution impact the certified configuration?	Official testing already complete
		What additional customer testing required?	
8. Release Planning	What's planned for this		

WYLE LABORATORIES, INC.  
 Huntsville Facility



<b>ORIGINAL NOTICE OF ANOMALY</b>		DATE: 09/16/2013
NOTICE NO: 7 (Rev A)	P.O. NUMBER: ES&S-MSA-TA029	CONTRACT NO: N/A
CUSTOMER: Election Systems and Software (ES&S)		WYLE JOB NO: T71013.01
NOTIFICATION MADE TO: Paul Huffman		NOTIFICATION DATE: 08/20/2013
NOTIFICATION MADE BY: Ryan Chambers		VIA: In person
CATEGORY: <input type="checkbox"/> SPECIMEN <input checked="" type="checkbox"/> PROCEDURE <input type="checkbox"/> TEST EQUIPMENT		DATE OF ANOMALY: 08/20/2013
PART NAME: EVS 4.5.0.0 FL		PART NO: ---
TEST: Low Temperature		I.D. NO: DS0313350009
SPECIFICATION: EAC 2005 VVSG, Volume II		PARA. NO: Section 4.6.4
<b>REQUIREMENTS:</b>		
<p>The low temperature test simulates stresses faced during storage of voting machines and ballot counters. All system components, regardless of type, shall meet the requirements of this test. This test is equivalent to the procedure of MIL-STD-810D, Method 502.2; Procedure 1-Storage. The minimum temperature shall be -4 degrees F. As outlined in the VVSG 4.6.4.2 Procedure, the following procedure is identified in Step 5: Allow the internal temperature of the equipment to stabilize at laboratory conditions before removing it from the chamber.</p>		
<b>DESCRIPTION OF ANOMALY:</b>		
<p>The technician removed the EUT from the environmental chamber approximately 1 hour after the internal temperature of the thermal chamber was returned to standard laboratory conditions. The technician did not allow the internal temperature of the equipment to stabilize at laboratory conditions before removing it from the chamber. As a result the accumulated moisture on the circuit board of the scanner assembly module caused a short circuit when the EUT was powered on. This anomaly was directly caused by human error in following the VVSG standard and the Wyle Operating Procedures.</p>		
<b>DISPOSITION • COMMENTS • RECOMMENDATIONS:</b>		
<p>The final disposition was to council and retrain all of the Wyle technicians on the associated Wyle Operating Procedure.</p>		
Safety Related <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Potential 10 CFR Part 21 <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	
RESPONSIBILITY TO ANALYZE ANOMALIES AND COMPLY WITH 10 CFR PART 21: <input type="checkbox"/> CUSTOMER <input checked="" type="checkbox"/> WYLE		
CAR Required: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	CAR No:	
VERIFICATION:	PROJECT ENGINEER: <i>Lynn Allus</i> 09/16/2013	
TEST WITNESS: <i>N/A</i>	PROJECT MANAGER: <i>Paul Padgett</i> 9/12/13	
REPRESENTING: <i>N/A</i>	INTERDEPARTMENTAL COORDINATION: <i>N/A</i>	
QUALITY ASSURANCE: <i>Beville</i> <i>Mason</i> 9/10/13		<i>N/A</i>

WH 1066, Rev. March '09

Page 1 of 1

WYLE LABORATORIES, INC.  
 Huntsville Facility





NOTICE OF ANOMALY		DATE: 08/30/2013
NOTICE NO: <u>8</u>	P.O. NUMBER: <u>ES&amp;S-MSA-TA029</u>	CONTRACT NO: <u>N/A</u>
CUSTOMER: <u>Election Systems and Software (ES&amp;S)</u>		WYLE JOB NO: <u>T71013.01</u>
NOTIFICATION MADE TO: <u>Paul Huffman</u>		NOTIFICATION DATE: <u>07/31/2013</u>
NOTIFICATION MADE BY: <u>Ryan Chambers</u>		VIA: <u>In person</u>
CATEGORY: <input checked="" type="checkbox"/> SPECIMEN <input type="checkbox"/> PROCEDURE <input type="checkbox"/> TEST EQUIPMENT	DATE OF ANOMALY: <u>07/31/2013</u>	
PART NAME: <u>EVS 4.5.0.0 FL</u>	PART NO. <u>---</u>	
TEST: <u>Electrostatic Disruption (ESD)</u>	I.D. NO. <u>DS0313350009</u>	
SPECIFICATION: <u>EAC 2005 VVSG, Volume I</u>	PARA. NO. <u>Section 4.1.2.8</u>	
<b>REQUIREMENTS:</b>		
<p>Vote scanning and counting equipment for paper-based systems, and all DRE equipment, shall be able to withstand <math>\pm 15</math> kV air discharge and <math>\pm 8</math> kV contact discharge without damage or loss of data. The equipment may reset or have momentary interruption so long as normal operation is resumed without human intervention or loss of data. Loss of data means votes that have been completed and confirmed to the voter.</p>		
<b>DESCRIPTION OF ANOMALY:</b>		
<p>Upon application of +15 kV air discharge to the top-right corner of the black plastic ballot tray cover, located closest to the front right of the DS200 screen. It was observed that the DS200 had become completely unresponsive and required human intervention, by means of a system reboot, to regain normal operation of the DS200. A clicking sound was observed during operation of the EUT, thus the shoeshine ballot was replaced with a new ballot and the clicking sound was resolved. After rebooting the EUT, the same test point was subjected to <math>\pm 2, 4, 8, 15</math> kV air discharge, at which time the EUT continued normal operation throughout the remainder of the test.</p>		
<b>DISPOSITION • COMMENTS • RECOMMENDATIONS:</b>		
<p>To ensure testing results were accumulated in accordance with the VVSG, the Electrostatic Disruption (ESD) was reperformed on 08/29/2013, for which there were no anomalies. The final disposition is that the original observance could not be replicated.</p>		
Safety Related <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO      Potential 10 CFR Part 21 <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A		
RESPONSIBILITY TO ANALYZE ANOMALIES AND COMPLY WITH 10 CFR PART 21: <input type="checkbox"/> CUSTOMER <input type="checkbox"/> WYLE		
CAR Required: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO      CAR No.		
VERIFICATION: TEST WITNESS: <u>N/A</u>	PROJECT ENGINEER: <u>[Signature] 08/30/2013</u> PROJECT MANAGER: <u>[Signature] 8/30/13</u>	
REPRESENTING: <u>N/A</u>	INTERDEPARTMENTAL COORDINATION: <u>N/A</u>	
QUALITY ASSURANCE: <u>[Signature] 8/30/13</u>	<u>N/A</u>	