The following bulleted items represent all documentation provided in the VotingWorks VxSuite 4.0 Technical Data Package (TDP).

- vx_tdp.pdf
- vx_user_manual.pdf
- README.txt
- VxSuite v4 VVSG2 Conformity Matrix.pdf
- VxSuite v4 VVSG2 Conformity Matrix.xlsx
- VX~00-10000-BOM.pdf
- VX~00-30000-BOM.pdf
- VX~00-00001_BOM.cvs
- anker-c300x-datasheet.pdf
- monoprice-5438-diagram.pdf
- tripp-lite-u360004slim-datasheet.pdf
- hp-elitebook-840-14in-g11-datasheet.pdf
- hp-elitebook-840-14in-g11-quick-specs.pdf
- hp-elitebook-840-14in-g11-regulatory-information.pdf
- hp-elitebook-840-14in-g11-service-guide.pdf
- hp-elitebook-840-14in-g11-user-guide.pdf
- hp-laserjet-pro-4001dn-datasheet.pdf
- hp-laserjet-pro-4001dn-user-guide.pdf
- ricoh-fi-760prb-user-guide.pdf
- ricoh-fi-7600-cleaning-guide.pdf
- ricoh-fi-7600-datasheet.pdf
- ricoh-fi-7600-safety-precautions.pdf
- ricoh-fi-7600-user-guide.pdf
- ricoh-fi-819prb-user-guide.pdf
- ricoh-fi-8170-cleaning-guide.pdf
- ricoh-fi-8170-datasheet.pdf
- ricoh-fi-8170-safety-precautions.pdf
- ricoh-fi-8170-user-guide.pdf
- apc-BN1500M2-datasheet.pdf
- apc-BN1500M2-user-guide.pdf
- hid-omnikey-R31210375-1-datasheet.pdf
- WAV-NKL001-datasheet.pdf
- WAV-NKL001-user-manual.pdf

- aaeon-UPN-ADLN97-A10-0864-datasheet.pdf
- adata-IM2P32A8-datasheet.pdf
- coolgear-CG-3510S4-datasheet.pdf
- cui-devices-ac-c13-na-datasheet.pdf
- elo-E968313.pdf
- fujitsu-FTP-62GDSL201-datasheet.pdf
- fujitsu-FTP-68EMCL-datasheet.pdf
- globtek-USBCW1M0USBC2SLEMBK-datasheet.pdf
- goldenmate_UPS_1000VA_600W.pdf
- hid-omnikey-R31210375-1-datasheet.pdf
- l-com-CAABLK-90RB-05M-datasheet.pdf
- lcom-ECF504-30-1AAS_2D.pdf
- meanwell-LRS-75-12-datasheet.pdf
- meanwell-LRS-150-24-datasheet.pdf
- pdi-ps6-datasheet.pdf
- piengineering-USB3SwitchInterface-DD.pdf
- piengineering-XK-A-1581-1BRD-R.pdf
- pui-audtio-AS07004PO-R -datasheet.pdf
- qualtek-719W-00_02 -datasheet.pdf
- sony-MDR-ZX110.pdf
- usb-firewire-RR-ADBU-XXGR-datasheet.pdf
- VX~00-10000.pdf
- VX~01-10001.pdf
- VX~01-10002.pdf
- VX~01-10003.pdf
- VX~01-10004.pdf
- VX~01-10005.pdf
- VX~01-10006.pdf
- VX~01-10034.pdf
- VX~01-10035.pdf
- VX~01-10036.pdf
- VX~01-10037.pdf
- VX~01-10048.pdf
- VX~01-10055.pdf
- VX~01-10060.pdf

- VX~01-10061.pdf
- VX~01-10062.pdf
- VX~01-10082.pdf
- VX~01-10083.pdf
- VX~01-10084.pdf
- VX~01-10085.pdf
- VX~01-10115.pdf
- VX~99-10018.pdf
- VX~99-10019.pdf
- VX~99-10020.pdf
- VX~99-10021.pdf
- VX~99-10022.pdf
- VX~99-10023.pdf
- VX~99-10024.pdf
- VX~99-10025.pdf
- VX~99-10026.pdf
- VX~99-10027.pdf
- VX~99-10028.pdf
- VX~99-10033.pdf
- VX~99-10046.pdf
- VX~99-10047.pdf
- VX~99-10051.pdf
- VX~99-10052.pdf
- VX~99-10053.pdf
- VX~99-10054.pdf
- VX~99-10058.pdf
- VX~99-10059.pdf
- VX~99-10074.pdf
- VX~99-10075.pdf
- VX~99-10077.pdf
- VX~99-10078.pdf
- VX~99-10079.pdf
- VX~99-10080.pdf
- VX~99-10081.pdf
- VX~99-10105.pdf

- VX~99-10106.pdf
- VX~99-10107.pdf
- VX~99-10108.pdf
- VX~99-10109.pdf
- VX~99-10110.pdf
- VX~99-10111.pdf
- VX~99-10112.pdf
- VX~99-10113.pdf
- VX~99-10117.pdf
- VX~99-10118.pdf
- VX~99-10119.pdf
- VX~99-10120.pdf
- VX~99-10122.pdf
- VX~99-10123.pdf
- VX~99-10124.pdf
- VX~99-10128.pdf
- VX~99-10130.pdf
- VX~99-10131.pdf
- VX~99-10132.pdf
- VX~99-10133.pdf
- VX~99-10134.pdf
- VX~99-10135.pdf
- VX~99-10136.pdf
- VX~99-10138.pdf
- VX~99-10139.pdf
- VX~99-10144.pdf
- VX~02-10007.pdf
- VX~02-10009.pdf
- VX~02-10010.pdf
- VX~02-10013.pdf
- VX~02-10014.pdf
- VX~02-10015.pdf
- VX~02-10016.pdf
- VX~02-10017.pdf
- VX~02-10029.pdf

- VX~02-10030.pdf
- VX~02-10031.pdf
- VX~02-10032.pdf
- VX~02-10038.pdf
- VX~02-10039.pdf
- VX~02-10040.pdf
- VX~02-10041.pdf
- VX~02-10042.pdf
- VX~02-10044.pdf
- VX~02-10045.pdf
- VX~02-10049.pdf
- VX~02-10050.pdf
- VX~02-10056.pdf
- VX~02-10057.pdf
- VX~02-10064.pdf
- VX~02-10065.pdf
- VX~02-10066.pdf
- VX~02-10067.pdf
- VX~02-10068.pdf
- VX~02-10069.pdf
- VX~02-10070.pdf
- VX~02-10071.pdf
- VX~02-10072.pdf
- VX~02-10073.pdf
- VX~02-10086.pdf
- VX~02-10087.pdf
- VX~02-10088.pdf

- VX~02-10090.pdf
- VX~02-10091.pdf
- VX~02-10092.pdf
- VX~02-10093.pdf
- VX~02-10094.pdf
- VX~02-10095.pdf
- VX~02-10096.pdf
- VX~02-10097.pdf
- VX~02-10098.pdf
- VX~02-10099.pdf
- VX~02-10100.pdf
- VX~02-10101.pdf
- VX~02-10102.pdf
- VX~02-10103.pdf
- VX~02-10104.pdf
- VX~02-10116.pdf
- VX~02-10121.pdf
- VX~02-10126.pdf
- VX~02-10127.pdf
- VX~02-10129.pdf
- VX~02-10137.pdf
- VX~02-10140.pdf
- VX~02-10143.pdf
- VX~01-30006.pdf
- VX~01-30016.pdf
- VX~02-30002.pdf
- VX~02-30005.pdf
- VX~02-30006.pdf
- VX~02-30007.pdf
- VX~02-30008.pdf
- VX~02-30009.pdf
- VX~02-30010.pdf
- VX~02-30011.pdf
- VX~02-30012.pdf

- VX~02-30013.pdf
- VX~00-00001.pdf
- VX~01-00002.pdf
- VX~01-00003.pdf
- VX~01-00004.pdf
- VX~01-00005.pdf
- VX~01-00006.pdf
- VX~01-00007.pdf
- VX~01-00008.pdf
- VX~01-00009.pdf
- VX~01-00010.pdf
- VX~01-00011.pdf
- VX~01-00012.pdf
- VX~01-00013.pdf
- VX~01-00014.pdf
- VX~01-00015.pdf
- VX~01-00016.pdf
- VX~01-00017.pdf
- VX~01-00018.pdf
- VX~01-00087.pdf
- VX~01-00099.pdf
- VX~01-00103.pdf
- VX~02-00019.pdf
- VX~02-00020.pdf
- VX~02-00021.pdf
- VX~02-00022.pdf
- VX~02-00023.pdf
- VX~02-00024.pdf
- VX~02-00025.pdf
- VX~02-00026.pdf
- VX~02-00027.pdf
- VX~02-00028.pdf
- VX~02-00029.pdf
- VX~02-00030.pdf
- VX~02-00031.pdf

- VX~02-00032.pdf
- VX~02-00033.pdf
- VX~02-00034.pdf
- VX~02-00035.pdf
- VX~02-00036.pdf
- VX~02-00037.pdf
- VX~02-00038.pdf
- VX~02-00039.pdf
- VX~02-00040.pdf
- VX~02-00041.pdf
- VX~02-00042.pdf
- VX~02-00043.pdf
- VX~02-00044.pdf
- VX~02-00045.pdf
- VX~02-00046.pdf
- VX~02-00047.pdf
- VX~02-00048.pdf
- VX~02-00049.pdf
- VX~02-00050.pdf
- VX~02-00051.pdf
- VX~02-00052.pdf
- VX~02-00053.pdf
- VX~02-00054.pdf
- VX~02-00055.pdf
- VX~02-00056.pdf
- VX~02-00057.pdf
- VX~02-00058.pdf
- VX~02-00059.pdf
- VX~02-00060.pdf
- VX~02-00061.pdf
- VX~02-00062.pdf
- VX~02-00063.pdf
- VX~02-00064.pdf
- VX~02-00065.pdf
- VX~02-00066.pdf

- VX~02-00067.pdf
- VX~02-00068.pdf
- VX~02-00069.pdf
- VX~02-00070.pdf
- VX~02-00071.pdf
- VX~02-00072.pdf
- VX~02-00073.pdf
- VX~02-00074.pdf
- VX~02-00075.pdf
- VX~02-00076.pdf
- VX~02-00077.pdf
- VX~02-00078.pdf
- VX~02-00079.pdf
- VX~02-00080.pdf
- VX~02-00081.pdf
- VX~02-00082.pdf
- VX~02-00083.pdf
- VX~02-00090.pdf
- VX~02-00091.pdf
- VX~02-00092.pdf
- VX~02-00093.pdf
- VX~02-00098.pdf
- VX~02-00100.pdf
- VX~02-00101.pdf
- VWX-001-D015-ScissorLink-AI.pdf
- VWX-001-D016-RearFrame-AI.pdf
- VWX-001-D017-FrontFrame-AI.pdf
- VWX-001-D018-Floor-AI.pdf
- VWX-001-D019-StorageStrap-AI.pdf
- VWX-001-D020-TubeNut-AI.pdf
- VWX-001-D021-E-BallotBin-AI.pdf
- VWX-001-D022-DoorLatch-AI.pdf
- VWX-001-D023-Door-AI.pdf
- VWX-001-D024-TorqueInsert-AI.pdf
- VXBOX-001-D013-Frame-AI.pdf

- VxBox-timeStudy.pdf
- WVX-001-D012-BallotBox-AI.pdf
- bmd-packing-instructions.pdf
- VX~00~30000-workplan.pdf
- VX~00~00001_workplan.pdf
- Software QA Checklists.pdf
- VxAdmin-Production-QA-Checklist.pdf
- VxCentralScan-Production-QA-Checklist.pdf
- VxMarkScan-Production-QA-Checklist.pdf
- VxScan-Production-QA-Checklist.pdf
- Root Cause Analysis (RCA) - Anker Solix UPS Failures in EMC Testing, Reproduced for VV40ECT-78_ Power Dips Tests.pdf
- Root Cause Analysis (RCA) - VV40ECT-74_ VxScan Radiated Electromagnetic Emissions (Class B) Failure at 54 MHz and 66 MHz.pdf
- Root Cause Analysis (RCA) - VV40ECT-75_ VxScan Radiated RF Immunity failure at 350-400MHz.pdf
- Root Cause Analysis (RCA) - VV40ECT-76, -168, -233, -240_ VxMarkScan ESD failures at PAT & ATI Inputs, Card Reader, and Rear Power.pdf
- Root Cause Analysis (RCA) - VV40ECT-77_ VxScan Electrical Fast Transient (EFT) Failure with Anker UPS.pdf
- Root Cause Analysis (RCA) - VV40ECT-87_ VxMark Unable to Save CDF Logs Due to Time Limit.pdf
- Root Cause Analysis (RCA) - VV40ECT-96_ Issue with Creating and Using a New System Administrator Card in VxAdmin.pdf
- Root Cause Analysis (RCA) - VV40ECT-98_ Overvotes Triggered on Scanners.pdf
- Root Cause Analysis (RCA) - VV40ECT-99_ UnderVote Appeared in VxScan.pdf
- Root Cause Analysis (RCA) - VV40ECT-100_ VxScan Ballot Jam Error For VxMark Ballots.pdf
- Root Cause Analysis (RCA) - VV40ECT-101_ VxScan Internal Connection Problem Printer is Disconnected.pdf
- Root Cause Analysis (RCA) - VV40ECT-130, -131, -132_ Scaled Ballots Causing VxScan Misinterpretation of Votes.pdf
- Root Cause Analysis (RCA) - VV40ECT-147_ VxScan Test Sound Button Bug.pdf
- Root Cause Analysis (RCA) - VV40ECT-151_ VxMark Stuck in Loop when Printed Ballot Cannot Be Interpreted.pdf

- Root Cause Analysis (RCA) - VV40ECT-157_ VxScan with APC battery is not capable of sustaining power for at least 2 hours.pdf
- Root Cause Analysis (RCA) - VV40ECT-192, -213_ VxScan Unable to Save CDF Logs.pdf
- Root Cause Analysis (RCA) - VV40ECT-203_ VxScan did not trigger an error on start up.pdf
- Root Cause Analysis (RCA) - VV40ECT-234_ VxScan Lightning Surge, Display stopped showing ballot on screen.pdf
- Root Cause Analysis (RCA) - VV40ECT-242_ VxMarkScan ESD Secure Boot Violation message required human intervention to continue.pdf
- VxScan-v3 NOVO Conducted Test Results-20240724.pdf
- VxScan-v3 NOVO Emissions Test Results-20240802.pdf
- VxScan-v3 NOVO Immunity Test Results-20240724.pdf
- VxScan-v3-v4 NOVO ESD Test Results-20240802.pdf
- VxScan-v4 Eurofins Safety Report - Approval Letter for US.pdf
- VxScan-v4 Eurofins Safety Report - Test Report UL 62368-1.pdf
- VxScan-v4 Nemko Vibration Testing - REP061410-ENV.pdf
- VxScan-v4 NOVO Emissions Test Results-20240723.pdf
- VxScan-v4 NOVO Radiated Emissions Testing - Test Notes 9-10-24.pdf
- VxScan-v4 NOVO Safety Test Results-20240724.pdf
- VxScan-v4 NOVO Vibration Test Results-20241008.pdf
- Test Report - VxMarkScan-v4 -- Bench Handling.pdf
- Test Report - VxMarkScan-v4 – Environmental.pdf
- Test Report - VxMarkScan-v4 -- Vibration and Transit.pdf
- Test Report - VxMarkScan-v4 T-Coil Adapter Compatibility.pdf
- Test Report - VxScan-v4 Ballot Box Material Cold Storage.pdf
- Test Report - VxScan-v4 Bulk Scan & Warm Operational Conditions.pdf
- Test Report - VxScan-v4 Cold Storage.pdf
- Test Report - VxScan-v4 Drop Test, Bench Handling.pdf
- Test Report - VxScan-v4 Feature Acceptance Criteria_ Administrative Functions.pdf
- Test Report - VxScan-v4 Feature Acceptance Criteria_ Paper Path, Ballot.pdf
- Test Report - VxScan-v4 Feature Acceptance Criteria_ Paper Path, Thermal Printer.pdf
- Test Report - VxScan-v4 Feature Acceptance Criteria_ Storage, Stacking, & Handling.pdf

- Test Report - VxScan-v4 Outdoor Cyclic Freezing & Full Sun Operation.pdf
- Test Report - VxScan-v4 Thermals with Updated Hardware_Software.pdf
- Test Report - VxScan-v4 Thermals.pdf
- VxScan Normal Function Checklist - 20240601 – Initial.pdf
- VxScan Normal Function Checklist - 20240903 - After Bulk Scan, Before Drop Test.pdf
- VxScan Normal Function Checklist - 20240903 - After Drop Test, Before Cold Storage.pdf
- VxScan Normal Function Checklist - 20240909 - After Cold Storage, Before Hot Storage.pdf
- VxScan Normal Function Checklist - 20240917 - After Hot Storage.pdf
- VxScan Normal Function Checklist - 20250219 - Before freeze.pdf
- VxScan Normal Function Checklist - 20250224 - After freezes.pdf
- VxScan Normal Function Checklist - 20250224 – Sunlight.pdf
- VxScan normal-function-test-ballot-example.pdf
- VxScan Paper Path Testing Raw Data - Build 0 Unit 2.pdf
- VxScan Tests of Normal Function.pdf
- vxsuite-v4-risk-assessment.pdf
- vxsuite-v4-risk-assessment.xlsx
- compute-system-hash.sh
- README-FIPS.md
- README-vx-iso.md
- VotingWorksLoggingDocumentation.md
- rust.md
- typescript.md
- VotingWorks COTS Report - v4.pdf
- VotingWorks COTS Report - v4.cvs
- VotingWorks COTS Report - v4.xlsx
- vxsuite-v4-pollworker-testing-report.pdf
- vxsuite-v4-uat-report.pdf
- vxsuite-v4-uat-report-vxscan-with-jacks.pdf
- App A PW Poll worker tester demographics.xlsx
- App B PW Informed Consent Form - Pollworker testing – 2024.pdf
- App C PW Poll Worker Testing Feedback Form - Google Forms.pdf
- App D PW official-precinct-ballot-Precinct_1-1_en.pdf

- App D PW official-precinct-ballot-Precinct_1-1_es-US.pdf
- App D PW official-precinct-ballot-Precinct_1-1_zh-Hans.pdf
- App D PW official-precinct-ballot-Precinct_1-1_zh-Hant.pdf
- App E Instructions for pollworker UAT.pdf
- App F PW Poll Worker Testing Feedback Form (Responses).xlsx
- App A Voter UAT Demographics.xlsx
- App B Voter Informed Consent Form - VxMark user testing - 2024 - Chinese, simplified.pdf
- App B Voter Informed Consent Form - VxMark user testing - 2024 - Chinese, traditional.pdf
- App B Voter Informed Consent Form - VxMark user testing - 2024 – Spanish.pdf
- App B Voter Informed Consent Form - VxMark user testing – 2024.pdf
- App C Voter UAT Data Collection Form - Google Forms.pdf
- App D Voter official-precinct-ballot-Precinct_1-1_en.pdf
- App D Voter official-precinct-ballot-Precinct_1-1_es-US.pdf
- App D Voter official-precinct-ballot-Precinct_1-1_zh-Hans.pdf
- App D Voter official-precinct-ballot-Precinct_1-1_zh-Hant.pdf
- App F Voter UAT Results.pdf
- App A Voter UAT Data Collection Form 2026 (responses).xlsx
- App B Voter Informed Consent Form - VxMark_VxScan UAT SF - 2026 - Chinese, simplified.pdf
- App B Voter Informed Consent Form - VxMark_VxScan UAT SF - 2026 - Chinese, traditional.pdf
- App B Voter Informed Consent Form - VxMark_VxScan UAT SF - 2026 – English.pdf
- App B Voter Informed Consent Form - VxMark_VxScan UAT SF - 2026 – Spanish.pdf
- App C Voter UAT Data Collection Form 2026 - Google Forms.pdf
- App D Voter official-precinct-ballot-Precinct_1-1_en.pdf
- App D Voter official-precinct-ballot-Precinct_1-1_es-US.pdf
- App D Voter official-precinct-ballot-Precinct_1-1_zh-Hans.pdf
- App D Voter official-precinct-ballot-Precinct_1-1_zh-Hant.psf
- App F Voter UAT Data Collection Form 2026 (responses).xlsx
- TRUST_Services_Agreement.pdf
- README.md
- VSAP-BOM.pdf
- VSAP_System_Hardware_Characteristics.pdf

- amt-9GP1007020-datasheet.pdf
- auo-G156HTN02_0-datasheet.pdf
- newland-NLS-EM3085-M-datasheet.pdf
- penmount-PM1415-datasheet.pdf
- vsap-ACS-100-datasheet.pdf
- BALLOT_BOX.pdf
- BMD.pdf
- KEYPAD_CONTROLLER.pdf
- STAND.pdf
- 20190823 - TOP_Housing.pdf
- Ballot_Box_Body.pdf
- Ballot_Box_Cradle.pdf
- Ballot_Box_Door.pdf
- BALLOT_BOX_LATCH.pdf
- BALLOT_BOX_LID.pdf
- BALLOT_BOX_MAGNET_RETAINER.pdf
- Bottom_Housing.pdf
- BOTTOM_SCAN_LENS.pdf
- Housing_Knuckle_Cover.pdf
- KEYPAD_ARROW_BUTTON.pdf
- KEYPAD_BOTTOM_HOUSING.pdf
- KEYPAD_BUMPER
- KEYPAD_BUMPER_BRACE.pdf
- KEYPAD_CABLE_TRAY.pdf
- KEYPAD_CAPTIVE_CABLE_OVERMOLD.pdf
- KEYPAD_CENTER_BUTTON.pdf
- KEYPAD_HELP_BUTTON.pdf
- KEYPAD_ROCKER_BUTTON_RATE.pdf
- KEYPAD_ROCKER_BUTTON_VOLUME.pdf
- Keypad_Top_Housing.pdf
- MONITOR_BACK_CASE.pdf
- MONITOR_BEZEL.pdf
- MONITOR_FRAME.pdf
- MONITOR_FRAME_LEFT.pdf
- MONITOR_FRAME_RIGHT.pdf

- MONITOR_HINGE.pdf
- MONITOR_HINGE_BRACKET_LEFT.pdf
- MONITOR_HINGE_BRACKET_RIGHT.pdf
- Monitor_Knuckle.pdf
- POLL_PASS_INDICATOR_LIGHTPIPE.pdf
- PRINTER_BASE.pdf
- Printer_Cover.pdf
- PRINTER_COVER_BUTTON.pdf
- PRINTER_COVER_HINGE_ARM_LEFT.pdf
- PRINTER_COVER_HINGE_ARM_RIGHT.pdf
- PRINTER_COVER_HINGE_BARREL.pdf
- PRINTER_COVER_LIGHTPIPE.pdf
- PRINTER_COVER_LIGHTPIPE_BACKER.pdf
- PRIVACY_SHIELD_CUP.pdf
- SPEAKER_CASE.pdf
- TOP_HINGE_BASE_LEFT.pdf
- TOP_HINGE_BASE_RIGHT.pdf
- TOP_Housing.pdf
- VSAP-workplan.pdf
- Bench Handling Test Report - SGS.pdf
- Electrical Test Report - NTS.pdf
- High Humidity Test Report - SGS.pdf
- High Temperature Test Report - SGS.pdf
- Vibration Test Report - SGS.pdf
- vxmarkscan_safety_test_20241219.pdf