



Formal Investigation Anomaly Status

EAC is currently conducting a Formal Investigation into four anomalies discovered in EAC certified voting systems. This chart depicts the status of the DS200 anomalies in the three EAC certified ES&S voting systems. Each version depicted below is a separate voting system.

Unity 3.2.0.0

System Submitted	System Certified	Time In Testing
March 19, 2007	July 21, 2009	2 years 4 months

Discovered Anomalies	Fixed
1. Freeze/shutdown	No
2. Failure to Log	No
3. Ballot Skew	No
4. Vote Miscount	No



DS200
 Software: v. 1.3.10.0
 Hardware: v. 1.2.0
 v. 1.2.1

Unity 3.2.0.0 Rev. 1

System Submitted	System Certified	Time In Testing
June 22, 2010	August 24, 2010	2 months 1 day

Discovered Anomalies	Fixed
1. Freeze/shutdown	No
2. Failure to Log	No
3. Ballot Skew	Yes
4. Vote Miscount	No



DS200
 Software: v. 1.4.5.0
 Hardware: v. 1.2.0
 v. 1.2.1

Unity 3.2.1.0

System Submitted	System Certified	Time In Testing
August 19, 2009	March 29, 2011	1 year 7 months

Discovered Anomalies	Fixed
1. Freeze/shutdown	Yes
2. Failure to Log	Yes
3. Ballot Skew	Yes
4. Vote Miscount	Yes



DS200
 Software: v. 1.4.3.11
 Hardware: v. 1.2.0
 v. 1.2.1