

ENGINEER CHANGE ORDER (ECO) ANALYSIS FORM

Manufacturer:	Dominion Voting Systems
System:	ICC Scanner Workstation
ECO Number:	100694
ECO Description:	Added DELL Optiplex 5270 AIO computer in an ICC 4.14.17 Scanner Workstation configuration due to the DELL Optiplex 3050 AIO, 7440 AIO, and 9030 AIO computers becoming commercially unavailable for purchase

Overview:

Added DELL Optiplex 5270 computer in an ICC Scanner Workstation configuration due to the DELL Optiplex 3050 AIO, Optiplex 7440 AIO, and Optiplex 9030 AIO computers becoming commercially unavailable for purchase. This product has been tested with Windows 10 Pro and is suitable for use with existing D-Suite configurations using Windows 10 Pro on the ICC Scanner Workstations.

Products Affected: ICC Scanner Workstation

ICC 4.14.17 has also been tested for its operation on this Windows 10 Pro platform with the Canon DR-G1130 scanner using compatible Kofax drivers. *Refer to Dominion's installation instruction document for implementing this configuration.* ICC 4.14.17 is used in D-Suite 4.14-D, 4.14-DS, 4.14-E, and Florida versions 4.14.37v1 and 4.14.37v2

ICC Canon Workstation:

DVS PN 198-000069 ICC AIO 21.5 IN. TOUCH DESKTOP (DELL OPTIPLEX AIO 5270), 8GB, 500GB HDD; WIN 10 PRO

Supporting Documentation:

ECO 100694 DELL Optiplex 5270 AIO.pdf (*Dominion ECO*) ID_ICC_ScannerDriverInstallation_4.14.pdf Dell_Optiplex_5270-aio_owners-manual.pdf 198-000069_OptiPlex_5270_AiO_Win10Pro_ICC.xlsx 198-000035_Dell_3050_Touch_AiO_Specification.xlsx

Engineering Recommendation:

Technical Documentation Review performed for recommendation. Replacement component is comparable to current component in form fit, and function; therefore, no testing is required.

Engineering Analysis: De Minimis	
Reviewer:	Approver:
Wendy Owens Printed Name	Michael L. Walker Printed Name
Wendy Owens Signature	Michael L. Walker Signature
05/05/2020 Date	